

Multi-function Display

There are two display modes: display mode 1 and display mode 2.

Multi-function display mode 1 includes the following functions:

Odometer

Tripmeter

Coolant temperature meter

Multi-function display mode 2 includes the following functions:

DAYS


Stopwatch

Mileage countdown

TODAY

Air temperature meter

To switch between the display mode 1 and display mode 2, while press and hold the left control button (2), then press and hold the right control button (3) for more than 2 seconds.



- (1) Multi-function display
- (2) Left control button
- (3) Right control button