


Odometer/Tripmeter Display (CB600F II)

The display (1) has two functions: odometer and tripmeter.

Push the button (2) to select the “ODO” or “TRIP” mode.

To reset the tripmeter, push and hold the button when the display is in the “TRIP” mode.



- (1) Odometer/Tripmeter display
- (2) Odometer/Tripmeter select and reset button

