


CBR1000F

DES. NO.	REV. DATE
6000	F. SA. U. DE
6100	G. F. ED. SO. AR. FI. SP. NO. N
6800	SW
7100	IT



- 1 LEFT TURN SIGNAL INDICATOR
- 2 RIGHT TURN SIGNAL INDICATOR
- 3 HEADLIGHT
- 4 OIL PRESSURE LIGHT
- 5 SIDE STAND INDICATOR
- 6 RIGHT TURN SIGNAL INDICATOR

- A 10A NEUTRAL-OIL-TEMP-TACHOMETER
- B 10A POSITION-HEADLIGHT
- C 20A HEADLIGHT
- D 10A MOTOR-STARTER
- E 20A TURN SIGNAL-STARTER RELAY BRAKE-CHORN-PASSING
- F 10A FUELING
- G 10A FAN MOTOR

- BLACK
- BROWN
- YELLOW
- BLUE
- LIGHT BLUE
- RED
- WHITE
- GRAY

SWITCH SWITCH

ON	PA	FA	M	WATT	TL	TL
OFF	OFF	OFF	OFF	OFF	OFF	OFF
COLOR	Y/B	B/W	B/W	B/W	B/W	B/W

CHORN SWITCH

FREE	NO	WATT	TL
PUSH	OFF	OFF	OFF
COLOR	B/W	B/W	B/W

PASSING SWITCH

FREE	PA	FA	M	WATT	TL	TL
PUSH	OFF	OFF	OFF	OFF	OFF	OFF
COLOR	B/W	B/W	B/W	B/W	B/W	B/W

TURN SIGNAL SWITCH

W	B	R	L	O
OFF	OFF	OFF	OFF	OFF
COLOR	B/W	B/W	B/W	B/W

CLIPPING SWITCH

W	TL	WATT	TK
OFF	OFF	OFF	OFF
COLOR	B/W	B/W	B/W

STARTER SWITCH

ST	WATT
FREE	OFF
PUSH	OFF
COLOR	Y/B

DOWN STOP SWITCH

NO	WATT
OFF	OFF
ON	OFF
COLOR	B/W

WIRING DIAGRAM

0030Z-MS2