


Carburetor Adjustment

1. Start and warm up the engine to normal operating temperature.
2. Set the engine idle speed to 1,300 rpm by adjusting the stop screw (1). Turning the stop screw in the (A) direction will increase the rpm, and turning in the (B) direction will result in a decrease.
3. Turn the pilot screw (2) clockwise until you hear the engine miss or decrease in speed, then counterclockwise until the engine again misses or decreases in speed. Set the screw exactly between these two extreme positions to adjust fuel mixture.
4. If idle speed changes after adjusting fuel mixture, readjust the idle speed by turning the stop screw.



Ajuste del carburador

1. Arranque y caliente el motor hasta llegar a la temperatura normal de funcionamiento.
2. Ajuste la velocidad del motor a 1.300 rpm cuando marche en vacío , mediante el tornillo de tope (1). Haga girar el tornillo de tope en la dirección(A), y la velocidad del motor será aumentada; y en la dirección (B), reducida.
3. Hagar girar el tornillo piloto (2) en el sentido del movimiento de las manecillas del reloj hasta que se siente un aumento de velocidad del motor, luego hágalo girar en el sentido inverso hasta que ocurra lo mismo. Fije el tornillo piloto en el punto exactamente medio de estas dos extremidades para obener la mejor mezcla de combustible.
4. Si la velocidad de marcha en vacío fluctua después de ajustar la mezcla de combustible, reajuste la velocidad de marcha en vacío haciendo girar el tornillo de tope.