


If you cannot restart a warm engine:

1. Place the motorcycle on its center stand and set the parking brake.
2. Open the throttle (1) $1/8$ – $1/4$ turn while starting the engine.



(1) Throttle

RUNNING-IN

During the first 1,000 km (600 miles), do not operate the motorcycle at more than 80% of the maximum speed.

Avoid full throttle operation, and do not operate for a long time at one speed.

During initial running-in newly machined surfaces will be in contact with each other and these surfaces will wear in quickly. Running-in maintenance at 1,000 km (600 miles) is designed to compensate for this initial minor wear. Timely performance of the running-in maintenance will ensure optimum service life and performance from the engine.