

Lap time recall mode

- The history of recorded lap time and the fastest lap time is displayed.
- The lap time is reset.

Fastest lap time (F-LAP) is minimum lap time.
Fastest lap time (F-LAP) excludes start and last lap time.

Each time **[SEL]** button is pressed, the display is switched F-LAP, LAP-01, LAP-02 ~ (ascending sequence).

Each time **[SET]** button is pressed, the display is switched, F-LAP, ~ LAP-02, LAP-01 (descending sequence).

Lap time reset

Press and hold **[SET]** button to display the "CLEAR" and then press **[SET]** button, measured lap time is all reset.

