


Previous lap number



Previous lap time

- 4 To end measurement, press and hold the **LAP** button.

To Restart the Measurement

Press the **LAP** button again. The stopwatch restarts measuring.

- u Measurement starts from the next lap.

To Check or Clear the Lap Time

Select the "LAP TIME" menu in the setting

mode. **➡P.55** **➡P.57**