

Instruments (Continued)

LAP DATA

The history of recorded lap time and information are displayed.

To display the other lap information, press the **[SEL ▲]** (up) or **[SEL ▼]** (down) button.

To display the maximum acceleration, maximum deceleration, maximum left bank

angle and maximum right bank angle information, press the **[LAP]** button.

To end the display of lap time history, press the **[MODE]** button. The display returns to the upper level hierarchy.

To use the Lap Timer  **P.86**

Best icon (Appears when the fastest lap time displayed.)

