
Previous lap number



Previous lap time

4 To end measurement, press and hold the LAP button.

To restart the measurement

Press the LAP button again. The stopwatch restarts measuring.

► Measurement starts from the next lap.

To Check or Clear the Lap Time

Select the "LAP TIME" menu in the setting mode. \triangleright P.55