


H 10

F-20

Rear cushion

Amortisseur arrière

Hinterer Stoßdämpfer



FR.

Item d'entretien	T.D.R.	N° de réf.	N° de pièce	Description	N° de reques						N° de série	Code de zone		
					Es	MHSOM Dg	Sw	Sj	Es	MHSOM Dg			Dw	
			52420-GE8-881	JOINT INFERIEUR D'AMORTISSEUR										
					AR.	1	-	-	-	-	-	-	2001125	AR
						-	-	1	-	-	-	-	1202701	
						-	-	-	1	-	-	-	1058456	
						-	-	-	-	1	-	-	1057981	
						-	-	-	-	-	1	-	1058832	
		6	52462-GE8-003	GUIDE DE RESSORT	1	1	1	-	-	1	-	-		AR,E,G,SW,2SV
						-	-	-	-	1	1		1060822	
		7	52462-GN3-701	GUIDE DE RESSORT				1	-	-	-		1060822	U
						-	-	-	-	1	-		1060823	
		8	52485-088-901	BAGUE CAOUTCHOUC D'AMORTISSEUR						1	-		1060823	U
					AR.	1	1	1	1	1	1			
		9	52486-GA7-003	COLLIER DE BAGUE COAUTCHOUC	1	1	1	1	1	1	1			
		10	52515-GC8-003	SIEGE A SUPERIEURE DE RESSORT	1	1	1	-	-	1	1			AR,E,G,SW,2SW
						-	-	-	-	1	1		1060822	
						-	-	-	-	-	1		1060822	U
		11	52517-178-003	CAOUTCHOUC DE BUTEE	1	1	1	1	1	1	1			
		12	93200-08032-0A	BOULON HEX., 8X32	1	-	-	-	-	-	-		2001262	AR
						1	1	1	-	-	-			E,G,SW,2SW
						-	-	-	1	-	-		1206700	
						-	-	-	-	1	-		1062848	
						-	-	-	-	-	1		1065076	U
						-	-	-	-	-	1		1063054	