

Nº	L.O.N.	Service Item	F.R.T.	Nº	Nº	8	9
1	210141	(5,7,9) Mainshaft, Transmission 4.0		1	23211- Mainshaft, Transmission (12T) GFP-900	1-	1
	210141A •	• Includes: Engine Removal and Installation			23211-	-	-
2	210142	Replace Countershaft Add 0.2 (3,6,8,10)		2	GFP- Countershaft B10	1	1
	210142 11 213135	Countershaft, Transmission 4.0			23221-	1-	-
21	2101C2	• Includes: Engine Removal and Installation • Replace Mainshaft Add 0.2		3	GFP-900 Gear, Countershaft Low (34T)	-	1
	2101C8	Sprocket, Drive 0.2			23221- GFP- B10	1	-
22	2101C5	Bearing, Mainshaft: Left 4.0		4	Bush, 20x9 5 23421- Gear, Mainshaft Second (17T) GFP-900	1	1
	2101C6	• Includes: Engine Removal and Installation			23421- GFP- B00	-	-
+		Bearing, Countershaft: Right 4.0		6	23421- Gear, Countershaft Second (29T) GFP- B10	-	1
		• Includes: Engine Removal and Installation			23422- GB4-770	-	-
		Bearing, Mainshaft: Right 4.0			23431- GFP-900	-	-
		• Includes: Engine Removal and Installation			23431- GFP- B00	-	-
		Bearing, Mainshaft: Both 4.2			23431- GFP- B10	-	-
		• Includes: Engine Removal and Installation			23441- GFP-900	-	-
					23441- GFP- B00	-	-
					23441- GFP- B10	-	-