


E-3
CAM SHAFT/VALVE



Service Item	F.R.T.	BOM Of Group Number: E-3 Model :: Splendor (Dec, 1993)			
		Ref No.	Part Number	Description	Req.
CAM SHAFT COMP.,	0.7	1	12209-GB4-685	SEAL, VALVE STEM	2
ARM, VALVE ROCKER	1.1	2	14100-KCC-900	CAM SHAFT COMP.,	1
(ONE OR ALL)	--				
VALVE	1.4	3	14431-035-020R	ARM, VALVE ROCKER	2
(ADD 0.2 FOR EACH)	--	4	14451-035-000	SHAFT, VALVE ROCKER ARM	2
(INC. REFACING)	--	5	14711-GN5-910L	VALVE INLET	1
(EXC. VALVE GUIDE REPLACEMENT)	--	6	14721-GF6-010L	VALVE EXHAUST	1
SPRING, VALVE INNER	1.2	7	14751-KCC-900	SPRING, VALVE OUTER	2
(ADD 0.1 FOR EACH)	--	8	14761-KCC-900	SPRING, VALVE INNER	2
(INC. RELATIVE PART)	--	9	14771-GB4-680	RETAINER, VALVE SPRING	2
BEARING, RADIAL BALL	0.8	10	14775-MA6-000	SEAT, VALVE SPRING OUTER	2
(ADD 0.1 FOR EACH)	--	11	14781-MA6-000	COTTER, VALVE	4
		12	90012-333-000R	SCREW, TAPPET ADJUSTING	2
		13	90206-001-000	NUT, TAPPET ADJUSTING	2