


E-2

CAM SHAFT / VALVE



Service Item	F.R.T.	Group Number: E-2 Model :: Ignitor (May, 2012)			
		Ref No.	Part Number	Description	Req.
* CAMSHAFT COMP.,	0.7	1	12209-GB4-682	SEAL VALVE STEM	2
* ARM COMP., VALVE ROCKER	0.8	2	14100-KVE-900	SHAFT COMP., CAM	1
(SAME TIME FOR TWO UNITS)	--	3	14430-KSP-910	ARM COMP., VALVE ROCKER	2
* BEARING, RADIAL BALL, 6001	0.9	4	14451-KRM-840	SHAFT, ROCKER ARM	2
* SPRING, VALVE	1.6	5	14711-KTE-910	VALVE INLET	1
(ADD 0.1 FOR EACH)	--	6	14721-KWF-900	VALVE EXHAUST	1
* VALVE EX	1.8	7	14751-KWF-840	SPG VALVE OUTER	2
(ADD 0.2 FOR EACH)	--	8	14761-KWF-840	SPG VALVE INNER	2
(INC. REFACING)	--	9	14771-KSP-910	RETAINER, VALVE SPRING	2
(EXC. VALVE GUIDE REPLACEMENT)	--	10	14777-KSP-910	SEAT, VALVE SPRING	2
		11	14781-MA6-000	COTTER, VALVE	4
		12	90012-KK3-830	SCREW, TAPPET ADJUSTING	1
		13	90206-250-000	NUT, TAPPET ADJUSTING	1
		14	91008-KTN-900	BRG. BALL RADIAL, 12 X 28 X 8	1
		15	91007-KTN-900		1