

D 13


E-15

Crankshaft • Piston

Vilebrequin • Piston

Kurbelwelle • Kolben

Cigüeñal • Pistón



BMA6-15

Item d'entretien	T.D.R.	N° de réf.	N° de pièce	Description	N° de requis CBX400 Fc F2		N° de série	Code de zone
			13327-MA6-004	PALIER C (BROWN TAIHO)	2	2		
			13328-MA6-003	PALIER D (GREEN DAIDO)	2	2		
			13328-MA6-004	PALIER D (GREEN TAIHO)	2	2		
			13329-MA6-003	PALIER E (YELLOW DAIDO)	2	2		
			13329-MA6-004	PALIER E (YELLOW TAIHO)	2	2		
			13330-MA6-003	PALIER F (PINK DAIDO)	2	2		
			13330-MA6-004	PALIER F (PINK TAIHO)	2	2		
			13331-MA6-003	PALIER G (RED DAIDO)	2	2		
			13331-MA6-004	PALIER G (RED TAIHO)	2	2		
		11	13610-MA6-000	CHAINE PRIMAIRE	1	1		
		12	91203-MA6-003	JOINT D'ETANCHEITE D'HUILE, 30X45X8	1	1		