


# CBR1000F (E)



0030Z-MZZ-6000

Wiring Diagram  
 1. 12V DC  
 2. 12V AC  
 3. 12V DC  
 4. 12V AC  
 5. 12V DC  
 6. 12V AC

