
Front Driveshaft Boots (Except TRX420TE1)

Refer to Safety Precautions on page 103.

FRONT



(1) driveshaft boots

Check the driveshaft boots (1) for cuts, damage or leaking grease. If necessary, have your dealer replace them.