

C 16


E-9

Crankshaft

Vilebrequin

Kurbelwelle

Cigüeñal



B149-9

WARTUNGSPUNKT	AP	REF.NR	TEILE-NR.	BESCHREIBUNG	MENGE CY50K2	SERIE-NR.	GEBIETS-CODE
		8	13312-149-010	SEITENPLATTE	1		
		9	13321-149-310	KURBELWELLE, L.	1		
		10	13381-149-000	KURBELSTIFT	1		
		11	14311-035-000	STEUERKETTENRAD (14T)	1		
		12	15441-149-000	OELDURCHGANG	1		
		13	15447-149-000	FEDER, OELDURCHGANG	1		
		14	90741-035-000	SCHEIBENKEIL, 3X5	1		
		15	91001-035-008	RADIALKUGELLAGER, 6304 (TOYO)	2		
		16	91101-149-000	PLEUELLAGER	1		
			91102-149-000	PLEUELLAGER	1		
			91103-149-000	PLEUELLAGER	1		
		17	91202-115-015	SIMMERRING, 19X36X7	1		
		18	91309-302-000	O-RING, 70X2.4	1		
		19	96220-20118	ROLLE, 2X11.8	1		

www.Honda.CY50.de