

H 11


F-20

Rear cushion

Amortisseur arrière

Hinterer Stoßdämpfer

← IFR.



Item d'entretien	T.D.R.	N° de réf.	N° de pièce	Description	N° de reques								N° de série	Code de zone
					S ₁	NH50M Dc	S ₂	NH50M Dc	S ₃	NH50M Dc	S ₄	NH50M Dc		
		•	93201-08032-0A	BOULON HEX., 8X32	1	-	-	-	-	-	-	-	2001263	AR
					-	-	-	1	-	-	-	-	1203701	
					-	-	-	-	1	-	-	-	1032849	
					-	-	-	-	-	1	-	-	1065076	U
					-	-	-	-	-	-	1	-	1063055	
		13	95800-10040-00	ROULON DE BRIDE, 10X40	1	1	1	1	1	1	1	1		

1989.02.10

E

H11