


E-2

Camshaft • Valve

Arbre a Cames • Soupape

Arbol de Levas • Valvula



KBBB-E0200

Service item	F.R.T	Ref. Nº	Part No.	Description	Qtd. XL200	Serial No.	Note
CAMSHAFT COMP0.9		1	12208-413-003	SEAL, VALVE STEM (ARAI)	2		
ARM, VALVE ROCKER *2.3		2	14100-KBB-900	CAMSHAFT COMP.	1		
(ADD 0.1 FOR EACH.)		3	14431-383-000	ARM, VALVE ROCKER	2		
(INC. RELATIVE PART)		4	14451-437-000	SHAFT, VALVE ROCKER ARM	2		
SPRING, VALVE *3.3		5	14456-383-000	PLATE, VALVE ROCKER ARM SHAFT SETTING	1		
(ADD 0.1 FOR EACH.)		6	14711-KBB-900	VALVE, IN.	1		
(INC. RELATIVE PART)		7	14721-KBB-900	VALVE, EX	1		
VALVE *3.5		8	14751-383-005	SPRING, VALVE OUTER (NIPPON HATSUJO)	2		
(ADD 0.2 FOR EACH.)		9	14761-383-005	SPRING, VALVE INNER (NIPPON HATSUJO)	2		
(INC. REFACING)		10	14771-107-020	RETAINER, VALVE SPRING	2		
(EXC. VALVE GUIDE REPLACEMENT)		11	14775-107-000	SEAT, VALVE SPRING OUTER	2		
		12	14776-107-010	SEAT, VALVE SPRING INNER	2		
		13	14781-MB4-000	COTTER, VALVE	4		
		14	90012-KN6-930	SCREW, TAPPET ADJUSTING	2		
		15	90206-250-000	NUT, TAPPET ADJUSTING	2		
		16	93600-06016-0A	SCREW, FLAT, 6X16	1		