

Service item	F.R.T.	Ref. N°	Part. No.	Description	No. Reqd. CBX250	Serial No.	Note
Horn Comp.0.1		1	30401-KPF-900	Cushion, C.D.I. Unit	1
Relay, Winker.....0.2		2	30410-KPF-901	C.D.I. Unit	1
Rectifier Assy., Regulator.....0.3		3	30500-KAN-T41	Coil Assy., Ignition.....	1
C.D.I. Unit.....0.4		4	30700-KPF-900	Cap Assy., Noise Suppressor	1
• Coil Assy., Ignition		5	31600-HN5-671	Rectifier Assy., Regulator	1
Harness, Wire1.3		6	31700-124-008	Rectifier Assy., Silicon (SHINDENGEN)	1
		7	31730-MAS-601	Diode Assy., Three Way (SUMITOMO)	1
		8	32100-KPF-900	Harness, Wire	1
		9	38120-MV8-901	Horn Comp. (LOW).....	1
		10	38301-KPF-900	Relay, Winker.....	1
		11	38306-KK4-000	Suspension, Winker Relay (MITSUBA).....	1
		12	90651-KV6-003	Band, Wire.....	1
		13	92101-05020-0A	Bolt, Hex., 5 x 20	2
		14	95701-06020-00	Bolt, Flange, 6 x 20	2
		15	95701-08012-00	Bolt, Flange, 8 x 12.....	1
		16	98200-41000	Fuse, Blade (10A).....	4
		17	98200-41500	Fuse, Blade (15A).....	2
Artículo de servicio	THLL	No. de N°	No. de pieza	Descripción	No. Rdo. CBX250	No. de serie	Nota
Ens Bocina.....0.1		1	30401-KPF-900	Cojin Unidade C.D.I	1
Rele Luz Intermitente.....0.2		2	30410-KPF-901	Unidade C.D.I.....	1
Ens Rectificador Regulador.....0.3		3	30500-KAN-T41	Bobina, Encendido.....	1
Unidad C.D.I.....0.4		4	30700-KPF-900	Ens Supresor Ruidos.....	1
• Ens Bobina Encendido		5	31600-HN5-671	Rectificador Regulador	1
Ens Alambraje1.3		6	31700-124-008	Regulador Silicio (SHINDENGEN).....	1
		7	31730-MAS-601	Diodo Comp., Tres Pólos (SUMITOMO).....	1
		8	32100-KPF-900	Alambraje Principal	1
		9	38120-MV8-901	Ens Bocina., (Grave)	1
		10	38301-KPF-900	Relé, Luz Intermitente.....	1
		11	38306-KK4-000	Soporte Relé, Luz Intermitente (MITSUBA)	1
		12	90651-KV6-003	Presilla, Fijación.....	1
		13	92101-05020-0A	Perno, Hex., 5 x 20	2
		14	95701-06020-00	Perno, Flange, 6 x 20	2
		15	95701-08012-00	Perno, Flange, 8 x 12	1
		16	98200-41000	Fusible(10A)	4
		17	98200-41500	Fusible (15A)	2