


G 3

F - 2

Meter



Service Item	F.R.T.	Ref. Part No.	Description	Req. QTY	Serial No.	Area code
				WTRNC		
				S	X	
SPEEDOMETER ASSY.....	0.4	1 34908-MB9-871	BULB, WEDGE BASE (12V 1.7W)...	1	1	
-SOCKET COMP.		2 34908-MG9-951	BULB, WEDGE BASE (12V 1.7W)...	3	3	
-BOX ASSY., PILOT		3 37200-KCR-003	SPEEDOMETER ASSY.....	1	-	
SPEEDOMETER COMP.....	0.5	4 37200-KCR-941	SPEEDOMETER ASSY.....	1	-	
BOSS, ELBOW.....	0.3	4 37202-KCR-003	SOCKET COMP.....	1	-	
-CABLE ASSY., SPEEDOMETER		5 37202-KCR-941	SOCKET COMP.....	1	-	
CABLE, INNER.....	0.1	5 37205-KCR-003	BRACKET.....	2	2	
		6 37210-KCR-003	SPEEDOMETER COMP.....	1	-	
		7 37211-KY2-711	BOSS, ELBOW.....	1	-	
		8 37211-KCR-900	BOSS, ELBOW.....	1	-	
		8 37216-GJ8-701	GROMMET.....	1	1	
		9 37220-KCR-003	KNOB.....	1	1	
		10 37226-MZ5-008	BAND, SELF LOCK.....	1	1	
		11 37244-MM4-000	RUBBER, SPEEDOMETER MOUNTING..	1	1	
		12 37264-MR7-008	SEAL.....	1	1	
		13 37562-KCR-003	SOCKET COMP.....	1	1	
		14 37600-KCR-650	BOX ASSY., PILOT.....	1	-	
		15 37600-KCR-961	BOX ASSY., PILOT.....	1	-	
		15 37601-KCR-650	BASE COMP.....	1	-	
		15 37601-KCR-961	BASE COMP.....	1	-	
		16 37606-MR1-008	COLLAR.....	2	2	
		17 37607-MR1-008	RUBBER, PILOT BOX SETTING.....	2	2	
		18 44830-KCR-000	CABLE ASSY., SPEEDOMETER.....	1	1	
		19 44831-KCR-300	CABLE, INNER.....	1	1	
		20 90020-GW3-850	SCREW-WASHER, 5X12.....	2	2	

